
Quick Guide: Mobile gas detector unit. Connecting detectors correctly.

Correct connection of detectors – please note # numbering!

Detectors must be under power for minimum 60 min. before operation.







Connector must be fully inserted, and the nut tightened.

Bygmarken 19 • DK-3520 Farum
+45 4567 0600 • info@geopal.dk • www.geopal.dk

PENDING ITS-I 23ATEXQ36745 DBI reg. no 233.301 DIC444QMS